

# LOUISIANA DEPARTMENT OF PUBLIC SAFETY & CORRECTIONS PUBLIC SAFETY SERVICES



#### OFFICE OF STATE FIRE MARSHAL

[9/8/22]

### **GUIDANCE NOTICE**

**ATTENTION:** Real Estate, Housing, and Construction Industry Representatives:

The top priority of the Louisiana State Fire Marshal's Office (SFM) is to protect life and property from the hazards of fire and explosion. We understand you share that priority, especially regarding residential homes, and we are eager to partner in ensuring all fire and life safety requirements are in place for Louisiana families.

Effective January 1, 2023, Act 458 of the 2022 Regular Session of the Louisiana Legislature ("Act") changes the fire and life safety requirements of one or two-family residential homes, relating to the presence of carbon monoxide (CO) detectors. In addition, the Louisiana Uniform Construction Code Council amended the International Residential Building Code ("IRC") with those changes also becoming effective on Jan. 1, 2023.

This Guidance Notice means to notify you of the Act 458 requirements and further provides fire and life safety industry best practice recommendations, relating to the presence of CO detectors in one or two-family dwellings.

#### **ACT 458 REQUIREMENT**

Every one or two-family house/dwelling sold and/or leased after January 1, 2023 shall have at least one operable, life-long, sealed battery carbon monoxide (CO) detector.

- The detector packaging should feature phrases including "life-long" OR "ten-year" AND "sealed battery" OR "sealed-in lithium battery."
- The device can be in combination with a smoke detector.
- One or two-family house/dwelling is defined as a building containing not more than two dwelling units in which one or each dwelling unit is occupied by members of a single family with not more than three outsiders, if any, accommodated in rented rooms.

However, certain home elements affect applicable requirements necessitating more than one CO detector and/or specific placement for the CO detectors. See the chart below:

8181 Independence Blvd. • Baton Rouge, LA 70806 • 1-800-256-5452 • (225) 925-4911 • www.lasfm.org

OSFM-LETTER Page 1 of 4

If a house	1 CO Alarm, No Specific Location	Multiple CO Alarms, Specific Locations
Has no gas service available	•	
Has gas service available but its inactive	•	
Is an existing home, built before Jan. 1, 2023, without a generator	•	
Is an existing home, built before Jan. 1, 2023, with a permanently-mounted, whole home standby generator (at time of installation)		•

For homes that require additional detectors in specific locations, there should be one, operable, life-long, sealed battery carbon monoxide (CO) detector inside of each separate sleeping room and one in the living/common area.

Accordingly, please see the information below regarding the SFM's recommendations for CO detector best practices in homes subject to Act 458:

## CO DETECTOR RECOMMENDATIONS

- When only one CO detector is required, its best location is near a sleeping area, preferably within 10 feet of a bedroom door.
- Ideally, a CO detector should be located on every occupied level of your home, especially occupied levels with fuel-burning appliances. The CO detector should be placed within 10 feet of each bedroom door (inside or outside of the room), within 10 feet of the door to an attached garage, and inside of any rooms located over an attached garage. CO detectors should NOT be placed inside of an attached garage.
- CO detectors should <u>NOT</u> be placed directly above or beside fuel-fired, heating, or cooking appliances or in or near humid areas like bathrooms. A CO detector should be placed at a distance of at least 15 feet or farther from these appliances and fireplaces.
- CO detectors should <u>NOT</u> be placed next to a window or exterior door.
- Installation heights vary by manufacturer. Therefore, it is advised to read the provided installation manual for each detector before placement.
- Choose placement locations that are free of obstructions where the detector will stay clean and protected from adverse environmental conditions.

8181 Independence Blvd. • Baton Rouge, LA 70806 • 1-800-256-5452 • (225) 925-4911 • www.lasfm.org

OSFM-LETTER Page 2 of 4

CO detectors should be tested monthly to ensure they are operational.

As this conversation surrounding carbon monoxide (CO) detection has become more prevalent, there has been additional attention to previously existing requirements in residential homes regarding the presence of smoke detectors. Accordingly, please see the information below regarding the legal requirements and the SFM's recommendations for smoke detectors in one and two-family dwellings across Louisiana:

## **SMOKE DETECTOR REQUIREMENTS**

Act 163 of the 2009 Regular Session of the Louisiana Legislature (R.S. 40:1581 (C) and (D)) revised the previous law regarding smoke detectors that had been effective since January 1992. Act 163, which became effective in January 2011, expanded the law to require smoke detectors in all one-and-two family dwellings at the time of sale or lease and requires:

• At a minimum, one operable ten-year, sealed lithium battery smoke detector.

## **SMOKE DETECTOR RECOMMENDATIONS**

- One smoke detector should be placed on every occupied level of a home, inside of every bedroom, and outside of sleeping areas, like a hallway, as well as in a common area like a living room.
- Smoke detectors should be mounted five inches from the corners of a room or five inches from where the ceiling and side walls meet.



8181 Independence Blvd. • Baton Rouge, LA 70806 • 1-800-256-5452 • (225) 925-4911 • www.lasfm.org

OSFM-LETTER Page 3 of 4

Please feel free to reach out to the SFM's points of contact for clarification of these topics:

- Chief Deputy Erin St. Pierre- erin.e.st.pierre@la.gov or 225-955-0508
- Public Affairs Director Ashley Rodrigue- ashley.rodrigue@la.gov or 225-620-5115

Thank you all for your assistance in helping us help you keep our state's families as safe as possible.

Chief Dan Wallis Louisiana State Fire Marshal

OSFM-LETTER Page 4 of 4